

CERVA 01020015 SANDPIPER RED

EN 420
EN 407
EN 388
EN 12477



PROTECTIVE GLOVES FOR WELDERS, TYPE A

Употреба: Ръкавиците са за заваръчна работа и защита от механични рискове в суха среда.

Маркировка:



2143 – нива на защита EN388:03

Протъръване: 2

Прорязване: 1

Прокъсване: 4

Прободане: 3

Чувствителност 3

313x3x – нива на защита EN407:04

Запалимост клас 3

Контактна топлина клас 1

Конвективна топлина клас 3

Лъжистка топлина клас X

Мали пръски разтопен метал клас 3

Големи количества разтопен метал клас X

EN12477+A1:05 TYPE A – номер на стандарта, година на издаване и вид на заваръчески ръкавици

01020015 SANDPIPER RED – артикул 11 – размер

2016 – дата на производство(година)

Инструкция за поддръжка и употреба: Пазете ръкавиците от топлинно изпълнение на разтворители и текилни изпарения, смазочни вещества, машинни и води. Замърсения ръкавици трябва да бъдат почиствани с чека и свободно оставени при стайна температура. Ръкавиците не се правят или химически почистват.

Внимание: Ръкавиците не трябва да се използват в места където съществува опасност от захващане от подвижни части на машини. Използвайте винаги ръкавици с правлен размер и преди всяко използване проверете тяхното състояние. Никога не използвайте повредени ръкавици. При чувствителни лица не е изключено дразнене на кожата. В момента не съществува стандартизиран метод за тестване на УВ преминаване на ръкавиците. Въпреки това ръкавиците са изработвани от материали които не допускат УВ преминаване. Ръкавиците не предизвикват от токов удар предизвикан от повредено оборудване или работа с електричество. Ако ръкавиците са мокри или при продължителна работа с изпотен ръце, защитните свойства намаляват и риска от токов удар е по-голям.

Warning: Gloves should not be used if there is a risk of entanglement with moving machinery parts. Protective properties relate only to the palm of the glove. Always use the correct size and before each use, check the condition of the gloves. Never use worn through, hardened or otherwise damaged gloves. In susceptible individuals, skin irritation may occur – in this case do not use the gloves any more.

At present, there is no standardised test method for detecting the UV penetration through the gloves' materials used. Nevertheless, the current methods to manufacture protective welding gloves do normally not allow the UV penetration. As well, welding settings up do not allow a welder protection in case of a direct contact with all low voltage parts, the gloves do not provide protection against electric shock caused by faulty equipment or work under electric voltage. If the gloves are wet, soiled or soaked with sweat, the electric resistance is reduced and the risk may increase.

Transport and storage: Gloves should be transported in the original packaging or in a plastic bag. Gloves should be stored in a cool, dry environment away from direct sunlight. Shelf life is 5 years from the date of manufacture in suitable conditions.

EC type certificate has been issued by a notified body No. 2369 VIPO a.s., Gen. Svobodu 1069/4, Partizánske, Slovak Republic

Manufacturer: CERVA GROUP a.s., Prúmyslová 483, 252 61 Jeneč, Czech Republic

01020015 SANDPIPER RED - article 11 – size 2016 - production date/year)

Maintenance and usage of safety gloves: Protect gloves against radiant heat, do not expose to organic solvents and their vapours, lubricants, fats, mineral oils and water. Remove rough dirt with a brush and let gloves dry freely at room temperature after use. Gloves cannot be machine washed or dry cleaned.

Warning: Gloves should not be used if there is a risk of entanglement with moving machinery parts. Protective properties relate only to the palm of the glove. Always use the correct size and before each use, check the condition of the gloves. Never use worn through, hardened or otherwise damaged gloves. In susceptible individuals, skin irritation may occur – in this case do not use the gloves any more.

At present, there is no standardised test method for detecting the UV penetration through the gloves' materials used. Nevertheless, the current methods to manufacture protective welding gloves do normally not allow the UV penetration. As well, welding settings up do not allow a welder protection in case of a direct contact with all low voltage parts, the gloves do not provide protection against electric shock caused by faulty equipment or work under electric voltage. If the gloves are wet, soiled or soaked with sweat, the electric resistance is reduced and the risk may increase.

Transport and storage: Gloves should be transported in the original packaging or in a plastic bag. Gloves should be stored in a cool, dry environment away from direct sunlight. Shelf life is 5 years from the date of manufacture in suitable conditions.

EC type certificate has been issued by a notified body No. 2369 VIPO a.s., Gen. Svobodu 1069/4, Partizánske, Slovak Republic

Manufacturer: CERVA GROUP a.s., Prúmyslová 483, 252 61 Jeneč, Czech Republic

01020015 SANDPIPER RED - article 11 – size 2016 - production date/year)

Maintenance and usage of safety gloves: Protect gloves against radiant heat, do not expose to organic solvents and their vapours, lubricants, fats, mineral oils and water. Remove rough dirt with a brush and let gloves dry freely at room temperature after use. Gloves cannot be machine washed or dry cleaned.

Warning: Gloves should not be used if there is a risk of entanglement with moving machinery parts. Protective properties relate only to the palm of the glove. Always use the correct size and before each use, check the condition of the gloves. Never use worn through, hardened or otherwise damaged gloves. In susceptible individuals, skin irritation may occur – in this case do not use the gloves any more.

At present, there is no standardised test method for detecting the UV penetration through the gloves' materials used. Nevertheless, the current methods to manufacture protective welding gloves do normally not allow the UV penetration. As well, welding settings up do not allow a welder protection in case of a direct contact with all low voltage parts, the gloves do not provide protection against electric shock caused by faulty equipment or work under electric voltage. If the gloves are wet, soiled or soaked with sweat, the electric resistance is reduced and the risk may increase.

Transport and storage: Gloves should be transported in the original packaging or in a plastic bag. Gloves should be stored in a cool, dry environment away from direct sunlight. Shelf life is 5 years from the date of manufacture in suitable conditions.

EC type certificate has been issued by a notified body No. 2369 VIPO a.s., Gen. Svobodu 1069/4, Partizánske, Slovak Republic

Manufacturer: CERVA GROUP a.s., Prúmyslová 483, 252 61 Jeneč, Czech Republic

01020015 SANDPIPER RED - article 11 – size 2016 - production date/year)

Maintenance and usage of safety gloves: Protect gloves against radiant heat, do not expose to organic solvents and their vapours, lubricants, fats, mineral oils and water. Remove rough dirt with a brush and let gloves dry freely at room temperature after use. Gloves cannot be machine washed or dry cleaned.

Warning: Gloves should not be used if there is a risk of entanglement with moving machinery parts. Protective properties relate only to the palm of the glove. Always use the correct size and before each use, check the condition of the gloves. Never use worn through, hardened or otherwise damaged gloves. In susceptible individuals, skin irritation may occur – in this case do not use the gloves any more.

At present, there is no standardised test method for detecting the UV penetration through the gloves' materials used. Nevertheless, the current methods to manufacture protective welding gloves do normally not allow the UV penetration. As well, welding settings up do not allow a welder protection in case of a direct contact with all low voltage parts, the gloves do not provide protection against electric shock caused by faulty equipment or work under electric voltage. If the gloves are wet, soiled or soaked with sweat, the electric resistance is reduced and the risk may increase.

Transport and storage: Gloves should be transported in the original packaging or in a plastic bag. Gloves should be stored in a cool, dry environment away from direct sunlight. Shelf life is 5 years from the date of manufacture in suitable conditions.

EC type certificate has been issued by a notified body No. 2369 VIPO a.s., Gen. Svobodu 1069/4, Partizánske, Slovak Republic

Manufacturer: CERVA GROUP a.s., Prúmyslová 483, 252 61 Jeneč, Czech Republic

01020015 SANDPIPER RED - article 11 – size 2016 - production date/year)

Maintenance and usage of safety gloves: Protect gloves against radiant heat, do not expose to organic solvents and their vapours, lubricants, fats, mineral oils and water. Remove rough dirt with a brush and let gloves dry freely at room temperature after use. Gloves cannot be machine washed or dry cleaned.

Warning: Gloves should not be used if there is a risk of entanglement with moving machinery parts. Protective properties relate only to the palm of the glove. Always use the correct size and before each use, check the condition of the gloves. Never use worn through, hardened or otherwise damaged gloves. In susceptible individuals, skin irritation may occur – in this case do not use the gloves any more.

At present, there is no standardised test method for detecting the UV penetration through the gloves' materials used. Nevertheless, the current methods to manufacture protective welding gloves do normally not allow the UV penetration. As well, welding settings up do not allow a welder protection in case of a direct contact with all low voltage parts, the gloves do not provide protection against electric shock caused by faulty equipment or work under electric voltage. If the gloves are wet, soiled or soaked with sweat, the electric resistance is reduced and the risk may increase.

Transport and storage: Gloves should be transported in the original packaging or in a plastic bag. Gloves should be stored in a cool, dry environment away from direct sunlight. Shelf life is 5 years from the date of manufacture in suitable conditions.

EC type certificate has been issued by a notified body No. 2369 VIPO a.s., Gen. Svobodu 1069/4, Partizánske, Slovak Republic

Manufacturer: CERVA GROUP a.s., Prúmyslová 483, 252 61 Jeneč, Czech Republic

01020015 SANDPIPER RED - article 11 – size 2016 - production date/year)

Maintenance and usage of safety gloves: Protect gloves against radiant heat, do not expose to organic solvents and their vapours, lubricants, fats, mineral oils and water. Remove rough dirt with a brush and let gloves dry freely at room temperature after use. Gloves cannot be machine washed or dry cleaned.

Warning: Gloves should not be used if there is a risk of entanglement with moving machinery parts. Protective properties relate only to the palm of the glove. Always use the correct size and before each use, check the condition of the gloves. Never use worn through, hardened or otherwise damaged gloves. In susceptible individuals, skin irritation may occur – in this case do not use the gloves any more.

At present, there is no standardised test method for detecting the UV penetration through the gloves' materials used. Nevertheless, the current methods to manufacture protective welding gloves do normally not allow the UV penetration. As well, welding settings up do not allow a welder protection in case of a direct contact with all low voltage parts, the gloves do not provide protection against electric shock caused by faulty equipment or work under electric voltage. If the gloves are wet, soiled or soaked with sweat, the electric resistance is reduced and the risk may increase.

Transport and storage: Gloves should be transported in the original packaging or in a plastic bag. Gloves should be stored in a cool, dry environment away from direct sunlight. Shelf life is 5 years from the date of manufacture in suitable conditions.

EC type certificate has been issued by a notified body No. 2369 VIPO a.s., Gen. Svobodu 1069/4, Partizánske, Slovak Republic

Manufacturer: CERVA GROUP a.s., Prúmyslová 483, 252 61 Jeneč, Czech Republic

01020015 SANDPIPER RED - article 11 – size 2016 - production date/year)

Maintenance and usage of safety gloves: Protect gloves against radiant heat, do not expose to organic solvents and their vapours, lubricants, fats, mineral oils and water. Remove rough dirt with a brush and let gloves dry freely at room temperature after use. Gloves cannot be machine washed or dry cleaned.

Warning: Gloves should not be used if there is a risk of entanglement with moving machinery parts. Protective properties relate only to the palm of the glove. Always use the correct size and before each use, check the condition of the gloves. Never use worn through, hardened or otherwise damaged gloves. In susceptible individuals, skin irritation may occur – in this case do not use the gloves any more.

At present, there is no standardised test method for detecting the UV penetration through the gloves' materials used. Nevertheless, the current methods to manufacture protective welding gloves do normally not allow the UV penetration. As well, welding settings up do not allow a welder protection in case of a direct contact with all low voltage parts, the gloves do not provide protection against electric shock caused by faulty equipment or work under electric voltage. If the gloves are wet, soiled or soaked with sweat, the electric resistance is reduced and the risk may increase.

Transport and storage: Gloves should be transported in the original packaging or in a plastic bag. Gloves should be stored in a cool, dry environment away from direct sunlight. Shelf life is 5 years from the date of manufacture in suitable conditions.

EC type certificate has been issued by a notified body No. 2369 VIPO a.s., Gen. Svobodu 1069/4, Partizánske, Slovak Republic

Manufacturer: CERVA GROUP a.s., Prúmyslová 483, 252 61 Jeneč, Czech Republic

01020015 SANDPIPER RED - article 11 – size 2016 - production date/year)

Maintenance and usage of safety gloves: Protect gloves against radiant heat, do not expose to organic solvents and their vapours, lubricants, fats, mineral oils and water. Remove rough dirt with a brush and let gloves dry freely at room temperature after use. Gloves cannot be machine washed or dry cleaned.

Warning: Gloves should not be used if there is a risk of entanglement with moving machinery parts. Protective properties relate only to the palm of the glove. Always use the correct size and before each use, check the condition of the gloves. Never use worn through, hardened or otherwise damaged gloves. In susceptible individuals, skin irritation may occur – in this case do not use the gloves any more.

At present, there is no standardised test method for detecting the UV penetration through the gloves' materials used. Nevertheless, the current methods to manufacture protective welding gloves do normally not allow the UV penetration. As well, welding settings up do not allow a welder protection in case of a direct contact with all low voltage parts, the gloves do not provide protection against electric shock caused by faulty equipment or work under electric voltage. If the gloves are wet, soiled or soaked with sweat, the electric resistance is reduced and the risk may increase.

Transport and storage: Gloves should be transported in the original packaging or in a plastic bag. Gloves should be stored in a cool, dry environment away from direct sunlight. Shelf life is 5 years from the date of manufacture in suitable conditions.

EC type certificate has been issued by a notified body No. 2369 VIPO a.s., Gen. Svobodu 1069/4, Partizánske, Slovak Republic

Manufacturer: CERVA GROUP a.s., Prúmyslová 483, 252 61 Jeneč, Czech Republic

01020015 SANDPIPER RED - article 11 – size 2016 - production date/year)

Maintenance and usage of safety gloves: Protect gloves against radiant heat, do not expose to organic solvents and their vapours, lubricants, fats, mineral oils and water. Remove rough dirt with a brush and let gloves dry freely at room temperature after use. Gloves cannot be machine washed or dry cleaned.

Warning: Gloves should not be used if there is a risk of entanglement with moving machinery parts. Protective properties relate only to the palm of the glove. Always use the correct size and before each use, check the condition of the gloves. Never use worn through, hardened or otherwise damaged gloves. In susceptible individuals, skin irritation may occur – in this case do not use the gloves any more.

At present, there is no standardised test method for detecting the UV penetration through the gloves' materials used. Nevertheless, the current methods to manufacture protective welding gloves do normally not allow the UV penetration. As well, welding settings up do not allow a welder protection in case of a direct contact with all low voltage parts, the gloves do not provide protection against electric shock caused by faulty equipment or work under electric voltage. If the gloves are wet, soiled or soaked with sweat, the electric resistance is reduced and the risk may increase.

Transport and storage: Gloves should be transported in the original packaging or in a plastic bag. Gloves should be stored in a cool, dry environment away from direct sunlight. Shelf life is 5 years from the date of manufacture in suitable conditions.

EC type certificate has been issued by a notified body No. 2369 VIPO a.s., Gen. Svobodu 1069/4, Partizánske, Slovak Republic

Manufacturer: CERVA GROUP a.s., Prúmyslová 483, 252 61 Jeneč, Czech Republic

01020015 SANDPIPER RED - article 11 – size 2016 - production date/year)

Maintenance and usage of safety gloves: Protect gloves against radiant heat, do not expose to organic solvents and their vapours, lubricants, fats, mineral oils and water. Remove rough dirt with a brush and let gloves dry freely at room temperature after use. Gloves cannot be machine washed or dry cleaned.

Warning: Gloves should not be used if there is a risk of entanglement with moving machinery parts. Protective properties relate only to the palm of the glove. Always use the correct size and before each use, check the condition of the gloves. Never use worn through, hardened or otherwise damaged gloves. In susceptible individuals, skin irritation may occur – in this case do not use the gloves any more.

At present, there is no standardised test method for detecting the UV penetration through the gloves' materials used. Nevertheless, the current methods to manufacture protective welding gloves do normally not allow the UV penetration. As well, welding settings up do not allow a welder protection in case of a direct contact with all low voltage parts, the gloves do not provide protection against electric shock caused by faulty equipment or work under electric voltage. If the gloves are wet, soiled or soaked with sweat, the electric resistance is reduced and the risk may increase.

Transport and storage: Gloves should be transported in the original packaging or in a plastic bag. Gloves

ČERVA 01020015 SANDPIPER RED

EN 420
EN 407
EN 388
EN 12477



NL LASHANDSCHOENEN, TYPE A

Omschrijving:
Lashandschoenen, vijf vingers, gemaakt van rundsplit met katoenen binnenvoering.
Verkrijgbaar in maat 11 volgens EN420:2003, EN388:2003 en EN12477+A1:2005.

Gebruik: Handschoenen geschikt voor lassers, bieden bescherming tegen mechanische risico's in droge omstandigheden.

Eigenschappen en markering:



Europese regelgeving



2143-beschermingsniveau EN388:03

Slijtvastheid:

2

Sneeuwverstand:

1

Scherstekte:

4

Perforatiereverstand:

3

Precisie:

3

313x3x - beschermingsniveau EN407:04

Ontvlambaarheid:

klasse 3

Contacthitte:

klasse 1

Geluidshitsite:

klasse 3

Stralingshitsite:

klasse X

Kleine spatten gesmolten metaal:

klasse 3

Grote hoeveelheden gesmolten metaal klasse X

EN12477+A1:05 TYPE A - normering + geschikt voor lassen

01020015 SANDPIPER RED - artikel

11 - maat

2016 - productiedatum (jaar)

Reiniging en onderhoud: Beschermt de handschoenen tegen stralingshitsite, niet blootstellen aan organische oplosmiddelen en dampen, smeermiddelen, vetten, minerale olie en water. Verwijder grof vuil met een borstel en laat handschoenen drogen bij kamertemperatuur na gebruik. Handschoenen kunnen niet worden gewassen of chemisch worden gereinigd.

Waarschuwing: Handschoenen mogen niet worden gedragen als er een risico bestaat op verstrengeling met bewegende onderdelen van machines. Gebruik altijd de juiste maat. Testen zijn uitgevoerd op de palm van de hand. Zowel nieuwe als reeds gebruikte handschoenen dienen grondig geinspecteerd te worden op mogelijke beschadigingen voor gebruik. Gebruik van handschoenen kan een huurdramatie of allergische reactie veroorzaaken bij mensen met een gevoelige huid. Indien er tijdens of na het dragen van de handschoenen een allergische reactie ontstaat, raadpleeg dan direct een arts. Op dit moment is er geen standaardisatie methode om de UV-penetraat door de handschoen te testen. Echter, de huidige methode om handschoenen te maken laat geen UV-straling door. De handschoenen gebruikt bij vlambooglassen, die beiden deze geen bescherming tegen elektrische schokken veroorzaakt door een defect aan het lasmateriaal of aan de elektrische spanning. Nette, bevuilde of door zweet doordrenkte handschoenen verminderen de elektrische weerbaarheid van de handschoen en verhogen het risico.

Transport en opslag: Handschoenen moeten worden vervoerd in de originele verpakking of plastic zak. Oplaaan in een koele, donkere en droge ruimte buiten het bereik van direct zonlicht. Indien juist opgeslagen zullen deze handschoenen maximaal 5 jaar hun fysieke eigenschappen behouden vanaf de fabricatiedatum. De gebruiksduur kan niet aangegeven worden en is afhankelijk van de toepassing en verantwoordelijksheid van de gebruiker. Deze dient zich te vergewissen van de geschiktheid van de handschoen voor het beoogde gebruik.

Certificering: Handschoenen moet worden vervoerd in de originele verpakking of plastic zak. Oplaaan in een koele, donkere en droge ruimte buiten het bereik van direct zonlicht. Indien juist opgeslagen zullen deze handschoenen maximaal 5 jaar hun fysieke eigenschappen behouden vanaf de fabricatiedatum. De gebruiksduur kan niet aangegeven worden en is afhankelijk van de toepassing en verantwoordelijksheid van de gebruiker. Deze dient zich te vergewissen van de geschiktheid van de handschoen voor het beoogde gebruik.

CE type certificaat: werd uitgegeven door erkende keuringsinstantie No. 2369 VIPO a.s., Gen. Svobodu 1069/4, Partizánske, Slovak Republic

Leverancier: CERVA GROUP a.s., Prúmyslová 483, 252 61 Jeneč, Tsjechië

NO SVEISEHANSKER, TYPE A

Beskrivelse:

Femingrete, beskyttelseshansker til sveise, laget av oksespalt. Hansene er hølforet. Størrelse 11. Hvert par er merket med produsentens logo, artikkellnummer, produksjonsdato samt pictogram for standardene EN 420:2003, EN 388:2003 og EN 12477+A1:2005

Bruk: Hansene er designet til sveisearbeid og mekaniske farer i terre omgivelser.

Funksjoner og merkning:



Mekanisk risikosikon



2143 - beskyttelsesnivå EN 388:03

Siltstyrke:

2

Gjennomskjæring:

1

Istykkerring:

4

Stikkmotstand:

3

Smidighet:

3

313x3x - beskyttelsesnivå EN 407:04

Antennellosestare:

klasse 3

Kontaktværme:

klasse 1

Isoleringsevne:

klasse 3

Stråleværme:

klasse X

Metallsprut, små:

klasse 3

Metallsprut, store:

klasse X

EN12477+A1:05 TYPE A - standardnummer, produksjonsår og sveisehansketsype

01020015 SANDPIPER RED - artikel#11 - størrelse

2016 - produksjonsår

Instruksjoner for vedlikehold og bruk av beskyttelseshansker:

Beskyttelseshansker mod strålevarme, utsett ikke hansene for organiske løsemidler og eller -damer, smøremedier, fet, mineraliske oljer eller vann. Etter bruk bør grovere tilsmussing fjernes med en fin børste. Hansene bør oppbevares lost utstrakt ved romtemperatur. Hansene er ikke egnet til vask eller kjemisk rensing.

Advarsel:

Hansene bør ikke brukes der hvor det er fare for at de kan vikles inn i bevegelige maskindeler. De beskyttelseshansker relaterer kun til hansens håndflate. Bruk aldri gjennomslitte, hårde eller på annen måte skadde hansker.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken. Imidlertid tilferer de gjeldende metodene for produksjon av sveisehanskets normal ikke gjennomtrengning av UV! Ved utferdelse av lysbueveringen er sveisen ikke beskyttet hvilket det er teknisk et farlig å gjøre.

For brukere som er spesielt følsomme, kan det forekomme hudirritasjon - hvis dette oppstår må hansken ikke brukes. For tiden finnes ingen standardisert testmetode for måling av UV-gjennomtrengning gjennom materiale som benyttes i hansken.